COMPLETION REPORT

1	Name of the Work	Improvements and maintenance of culvert at Prashanth Nagara in ward No 13, Shettyhalli Sub Division.
2	Sanctioned Estimate No. and date	EE/DD/TS/67/18-19 Dated: 30.01.2019.
3	Head of Account which is chargeable	P1771 (Job Code 013-20-000011)
4	Instrument Order No. and date	EE/DD/WO/ 404 /19-20 dated: 27.09.2019
5	Name of Contractor	Sri S.N. Shankarappa.
6	Work started	16.12.2019
7	Work Completion	23.01.2020
8	Time Stipulated for Completion of Work	90 days
9	Delay in Execution of Work	
10	Measurement recorded in	MB No. 636 Page No. 63527 to 63531
11	Check Measurement of the Asst	23.01.2020
12	Name of the office/official in charge of the work	-
	a) Asst. Eng/Junior Engineer	Venkateshappa, AE
	b) Asst. Executive Engineer	H. Kumarappa, AEE

Sanctioned Estimated Amount	Amount Claims as per actually Vide as per bills	Excess	Savings
Rs. 10.00 Lakhs	~~6,69303.00~~ ~~6,86870.00~~ 686078.00	-	230697.00

Certified that the above has been completed within the stipulated time noted in the
Certified that the contractor has delayed and completed the work for which necessary fine recovered
Certified that the above work has been executed by the contractor satisfactory in

Assistant Engineer
Ward no.13

Asst.Executive Engineer
Shettyhalli sub division
ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Executive Engineer
Dasarahalli Division

EXECUTIVE ENGINEER
Bruhat Bangalore Mahanagara Palike
Dasarahalli Division, Bangalore-560057

Scanned by CamScanner